

SAS Superstructure

Location: 04-SF-80-13.2 / 13.9 Client Name: CalTrans **Run date** 19-Nov-14 **Time** 6:00 PM

Daily Diary Report by Bid Item

Contract No.: 04-0120F4

Diary #: 069 Const Calendar Day: 274 Date: 09-Jun-2010 Wednesday Inspector Name: Bruce, Matt Title: Transportation Engineer

04-0120F4 04-SF-80-13.2/13.9 Self-Anchored Suspension Bridge

Inspection Type: Continuous

Shift Hours: 07:00 am 03:30 pm Break: 00:30 Over Time:

Federal ID: Location:

Reviewer: Mathur, Lalit Approved Date: 08-Oct-10 Status: Approved

Weather

04-0120F4

Temperature 7 AM 50 - 60 **12 PM** 60 - 70 **4PM** 50 - 60

Precipitation 0.00" Condition Partly overcast and windy

Working Day 🗸 If no, explain:

Bid Item: 034

Diary:

Work description.

- Continued to work on stressing paperwork and prepare for upcoming stressing operations.

X-W2C-BCT.034

- Shot the elevations for the centerline north/south offets for OBG lifts 4W/5W panel points 24, 28, 30, and 36 using the automatic level with the assistance of Sami Daouk. This was done while the ROOT weld was in progress for the top joint between these two OBG lifts.

	SCHWAGER DAVIS INC.									
	Labor									
	Trade	Class	Name	RT Hrs	OT Hrs	DT Hrs	Total	Remarks	1	Dispute
Contractor: SCHWAGER DAVIS INC.										
	Ironworker	JNM	Brian Nobile	0.00	0.00	0.00	0.00			
	Ironworker	JNM	Todd Blackwell	0.00	0.00	0.00	0.00			
	Ironworker	JNM	Bobby Almon	0.00	0.00	0.00	0.00			
	Ironworker	JNM	Bounthaby Singharath	0.00	0.00	0.00	0.00			
	Ironworker	FOR	Erin Jones	0.00	0.00	0.00	0.00			
	Ironworker	JNM	James Bond	0.00	0.00	0.00	0.00			
	Ironworker	JNM	Randy Hill	0.00	0.00	0.00	0.00			
	Ironworker	GEN	Ralph Craig	0.00	0.00	0.00	0.00			

E-W Line Cross Over W2 Cap Cap Beam Continuity Tendons

Diary:

Work description.

034 X-W2C-BCT.034

- Pushed from strand packs number 8703, 8674, 8695, and 8700 into continuity tendons E30A to E42A.
- Stressed continuity tendons E19A and E25A using the monostrand ram 6-8-134 with gauge A. Lalit assisted me with the stressing operations inspection today.
- Continued installing the anchorheads and wedges on both the dead and live ends of the E-Line continuity tendon strands previously placed.
- Cut the live end strand tails of continuity tendons E20A to E24A and placed grout caps and tubes at the live end of these tendons.

The following is the list of equipment that SDI has onsite since it is not currently inputted into PMIV:

Stressing Rams: 6-8-0014, 6-8-134, and CH600-8-109

Hydraulic Pumps for Monostrand Rams: 2 units with no designated numbers on the equipment Hydraulic Pumps for Multistrand Rams: 1 unit with no designated numbers on the equipment

Hydraulic Pump for Pushing Strand: HPU-D-110-3K-02



Page 1 of 2

Daily Diary Report by Bid Item

Job Name: 04-0120F4 Inspector Name: Bruce, Matt Diary #: 069 Date: 09-Jun-2010 Wednesday

Strand Pusher: No number designated on the equipment Grout Pump: No number designated on the equipment

- Refer to other Caltrans inspectors diaries for ABF operations and equipment at the W2 cap beam.

Attachment



Grouting pump arrived onsite today.



ABF engineers and labors seen trying to remove the mandrel lodged in the pipe of continuity tendon E41B.